

# Uninterruptable Power Supply

The UPS System is available on all Thermwood machines.

The UPS system provides the user with many benefits. Its primary use is to provide power to the control in the case of a power outage. It can supply the control with power for up to 5 minutes after the main power goes out. This allows the operator to save any files that need saving and to power down the control in a controlled manner. The machine cannot be operated, only the control has reserve power. It also provides a measure of lighting and surge protection to the control.

The system will power the control only for up to 5 minutes, depending on the condition of the battery. The unit will take 4 hours to fully recharge in the case of a total draw down.



**CNC Router**  
*Retrofits*

800•221•3865  
Ext. 251

**thermwood**  
*First in CNC Routers*

PO Box 436, Dale, IN 47523  
812•937•4476, Fax 812•489•1144  
[www.thermwood.com](http://www.thermwood.com)